



FIG. 1



- A - Conductive Paint of Area "A" cm^2
- B - Sample Thickness (cm)
- C - DC Resistance (Ω)

FIG. 2



D - Notch

E - Piece Broken at 77K